

2215 E 03

HUMBER RIVER & TRIBUTARIES  
DRY WEATHER OUTFALL STUDY  
APPENDIX C: Field Data Sheets

Volume 5

PREPARED FOR  
ONTARIO MINISTRY OF THE ENVIROMENT  
BY  
GARTNER LEE ASSOCIATES LIMITED

Project No: 82-69  
March, 1983



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 601 Date: 27/10/82 Time: \_\_\_\_\_ Crew: \_\_\_\_\_

Weather: Today - Sunny & clear

Yesterday - "

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ 2M south of Maple leaf Dr bridge on  
(Sketch on back) the east bank

Outfall Description: Size - 1-300 i - 110 @ W x H - \_\_\_\_\_

Material - CIP Shape - \_\_\_\_\_

Active: Y/(N) Photographed: (Y) N #: Box 17-28

Samples Collected: Bacteria Routine Chemical

No we Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

No we Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

No we pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity \_\_\_\_\_ umhos


Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: - #: BC 85







# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 305 Date: 2-11-82 Time: 2.30 Crew: DM, LSH

Weather: Today - Sunny & Clear

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ 20 m north of MAPLE LEAF DR & HURON  
(Sketch on back) west side of BLACK CREEK DR.

Outfall Description: Size - 1150 (Ø) W x H - \_\_\_\_\_

Material - Concrete Shape - \_\_\_\_\_

Active: (Y) N Photographed: (Y) N #: Loc 17-36

Samples Collected: Bacteria Routine Chemical

1/2 l / sec

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: ~18 °C

pH: 7.9 Water Temp.: \_\_\_\_\_ °C

Conductivity: 1100 umhas

Observations: Colour Odour Erosion Impacts Land Use Other:

- clear No No No

- white film on surface

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boot Only

Is outfall otherwise mapped? Map: - #: as #243





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 609 Date: 8/18/82 Time: \_\_\_\_\_ Crew: AMTH

Weather: Today - Cloudy & Cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ underneath the 400 bridge on the  
(Sketch on back) west side of the south side of  
the bridge

Outfall Description: Size - 400 @ W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: C/N Photographed: C/N #: Roll 17-31

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Variable Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

- dense No No No

- pipe elevated

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: PC 105



1. The first part of the document is a letter from the President of the United States to the Congress, dated January 1, 1801. It is a very important document, as it is the first official communication of the new administration. The letter is written in a formal, dignified style, and it contains a great deal of information about the new government and the President's plans for the future.

2. The second part of the document is a letter from the President to the Congress, dated January 1, 1801. It is a very important document, as it is the first official communication of the new administration. The letter is written in a formal, dignified style, and it contains a great deal of information about the new government and the President's plans for the future.

# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 607 Date: 20/10/82 Time: 3:45 Crew: D. J. J. "

Weather: Today - Sunny & Clear

Yesterday - "

River: Humber Main Black Creek Humber West Other:                     

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: at the end of J. J. J. Creek  
(Sketch on back)

Outfall Description: Size - 50 ? Ø W x H -                     

Material - steel ? Shape -                     

Active: Y/N Photographed: Y/N #: REL 17-13

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other Phenol

Flow Rate: Velocity -                     

~0.5 l/sec Depth -                     

Sketch cross-section shape (on back)

Field Tests: D.O.:                      mg/L Air Temp.: 20 °C

pH: 7.8 Water Temp.:                      °C


Conductivity: 1600 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

- clear fresh No. No.

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map:                      #:



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 611 Date: 8/1/52 Time: \_\_\_\_\_ Crew: JM TT

Weather: Today - \_\_\_\_\_

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M ☒ N O P Q

Location: ~ on the inside of the 401 bridge  
(Sketch on back) at the apex ~ center of the bridge  
in the fishing

Outfall Description: Size - 400 ☒ W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y ☒ N Photographed: ☒ N #: BC 17-32

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road \* Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 106



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 613 Date: 8/11/82 Time: \_\_\_\_\_ Crew: D.M. + S.H.

Weather: Today - Clear & Cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: on the inside of the 401 bridge on the west side, E. side.  
(Sketch on back)

Outfall Description: Size - 400 (Ø) W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: Roll 17-33

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: 1/10 & 1/30 Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: GC 107





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 615 Date: 8/11/82 Time: \_\_\_\_\_ Crew: DM

Weather: Today - Clear & Cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: - @ the south west corner of the Courville Ave bridge  
(Sketch on back)

Outfall Description: Size - 400 W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: Roll 17-34

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 110

Jane

4

0

1

#65

4

# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 517 Date: 8/11/82 Time: \_\_\_\_\_ Crew: D.M. Smith

Weather: Today - 1. on a cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ @ the north west corner of intersection of  
(Sketch on back) Danwin Ave bridge East of Dan St

Outfall Description: Size - 400  $\phi$  W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y / N Photographed: GP N #: Reel 17-35

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 111



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 619 Date: 5/14/82 Time: \_\_\_\_\_ Crew: D.M. & T.H.

Weather: Today - Clear & Cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N Q P Q

Location: the north east corner of the  
(Sketch on back) Danvers Ave bridge, east of Hwy 401

Outfall Description: Size - 300 Ø, W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: R001736

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 112



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 721 Date: 8/11/82 Time: \_\_\_\_\_ Crew: D. T. T. H.

Weather: Today - Clear & Cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N OPQ

Location: ~ 120 m south of Williamsburg Bridge on the  
(Sketch on back) east bank, near the southwest  
corner of 1537 Wilson

Outfall Description: Size - 200  $\phi$  W x H - \_\_\_\_\_

Material - CMF Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: Rose 19-1

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 123 Date: 3/11/82 Time: \_\_\_\_\_ Crew: D. Y. 151

Weather: Today - cloudy & cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ 90m south of old bridge on west bank  
(Sketch on back)

Outfall Description: Size - 450 Ø W x H - \_\_\_\_\_

Material - CM Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: RC 12-2

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: RC 115



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 125 Date: 3/11/52 Time: \_\_\_\_\_ Crew: D.M.C. 511

Weather: Today - Clear & Cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N Q P Q

Location: ~ 60 m south of Victoria Ave bridge  
(Sketch on back) on the west bank

Outfall Description: Size - 200 W x H - \_\_\_\_\_

Material - Concrete Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: 125 3

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 116



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 027 Date: 5/11/82 Time: \_\_\_\_\_ Crew: D.M. & J.H.

Weather: Today - Ok & Cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ 30 south of Wilson Ave bridge  
(Sketch on back) on the east bank at the north  
west corner of #1537 Wilson Ave

Outfall Description: Size - 100 Ø W x H - \_\_\_\_\_

Material - G.I.P. Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: Rev 13-9

Samples Collected: Bacteria Routine Chemical

Metals Organic

None

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 117



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 637 Date: 8/1/82 Time: \_\_\_\_\_ Crew: DM LTH

Weather: Today - Clear Cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: On the north west corner of the Wilson Ave bridge, east of main st  
(Sketch on back)

Outfall Description: Size - 300 (Ø) W x H - \_\_\_\_\_

Material - stone Shape - \_\_\_\_\_

Active: Y/N Photographed: (Y) N #: ROU-5

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 117

21

1880-1881

1. The first part of the year was spent in the field, collecting specimens and making observations on the habits of the various species of birds and mammals. The weather was generally favorable, but there were some periods of heavy rain which prevented us from going out.

2. The second part of the year was spent in the laboratory, preparing the specimens and making up the reports. The work was very tedious, but it was necessary to do it in order to have the specimens properly preserved and the reports ready for publication.

3. The third part of the year was spent in the field again, making a few more collections and observations. The weather was not so good as in the first part of the year, but we were able to get some good results.



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 631 Date: 8/11/82 Time: \_\_\_\_\_ Crew: B. Y. & J. H.

Weather: Today - Clear & Cool

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: At the north east corner of the Danforth

(Sketch on back) bridge (North of Wilson) underneath

the bridge

Outfall Description: Size - 300 (Ø) W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y (N) Photographed: (Y) N #: 10011-6

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 125

	<p>RECEIVED</p> <p>JAN 10 1900</p>
<p>TO THE</p>	<p>SECRETARY OF THE</p>
<p>NAVY</p>	<p>DEPARTMENT</p>
<p>WASHINGTON</p>	<p>DC</p>
<p>FROM</p>	<p>THE</p>
<p>NAVY</p>	<p>DEPARTMENT</p>
<p>WASHINGTON</p>	<p>DC</p>
<p>DATE</p>	<p>JAN 10 1900</p>
<p>TIME</p>	<p>10 10 AM</p>

# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 233 Date: 9/11/82 Time: \_\_\_\_\_ Crew: B.Y.C.H.

Weather: Today - Overcast & cool

Yesterday - Sunny & cool

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ 5 m west of Lane St, Ch. on the west  
(Sketch on back) bank

Outfall Description: Size - 200 W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: Y/N N Photographed: Y/N #: 200-7

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 635 Date: 9/11/82 Time: \_\_\_\_\_ Crew: \_\_\_\_\_

Weather: Today - \_\_\_\_\_

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: - 300 m north of the mill race (down)

(Sketch on back) (June 1st & North of Wilson) on the

sand bank

Outfall Description: Size - 300  $\phi$  W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: Y/N: N Photographed: Y/N: Y #: 12-17-5

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 130



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 637 Date: 5/11/82 Time: 11:00 Crew: 10 & 11

Weather: Today - Overcast

Yesterday - Sunny

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q [Approx 30m west]

Location: Below Etobicoke Creek on E. bank

(Sketch on back) Approx. 30m west of discol # 331

Outfall Description: Size - Unknown W x H - ?

Material - Concrete Shape - \_\_\_\_\_

Active: Y/N trickie Photographed: Y/N #: Rel 10 - #7

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Slough 1/2 sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: Very bulky discharge

Discharge of ground water discharge - surface

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only Rel 10

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: Rel 137





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 637 Date: 9/11/82 Time: \_\_\_\_\_ Crew: D.M. & T.H.

Weather: Today - Overcast

Yesterday - Sunny

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N OPQ

Location: ~ on the south side of the south avenue going  
(Sketch on back) under Jane St. & the North end  
of OAKDALE GOLF COURSE

Outfall Description: Size - 200  $\phi$  W x H - \_\_\_\_\_

Material - Con Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: Row 19-10

Samples Collected: Bacteria Routine Chemical

311 sec Metals Organic  
Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: 7.8 mg/L Air Temp.: ~13 °C

pH: 7.8 Water Temp.: 11 °C

Conductivity: 1550 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

colour 10: 10: 10: 10: 10: 10:

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC144



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 641 Date: 9/11/82 Time: \_\_\_\_\_ Crew: DY-1-H

Weather: Today - Overcast

Yesterday - Sunny

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ 50M south of 6<sup>th</sup> Street Purchase

(Sketch on back)

Outfall Description: Size - 450  $\phi$  W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: Rec 19-11

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

1.22/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: 8.0 mg/L Air Temp.: 23 °C

pH: 7.8 Water Temp.: 10 °C

Conductivity: 1600 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 146

P  
U  
R  
C  
H  
A  
S  
E

GILTSBUR D12

S S



#641



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 643 Date: 9/11/82 Time: \_\_\_\_\_ Crew: 241311

Weather: Today - Overcast

Yesterday - Clear

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ south of Peterdale

(Sketch on back)

Outfall Description: Size - 300 W x H - \_\_\_\_\_

Material - CLP Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: Reel 19-12

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: 11 litres/sec. Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: 13 °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: 200 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

Clear (great) ABUTMENT HAS SLID  
Simply DOWN SIDE OF HILL, BREAKING  
PIPE

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 145



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 645 Date: 10/11/82 Time: 11:00 Crew: JH & DM

Weather: Today - overcast

Yesterday - clear

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: NATURAL SPRINGS - 2 LOCATIONS:

(Sketch on back) ON N BANK, Below last parking lot  
in driveway - hills

Outfall Description: Size - INDETERMINATE  $\phi$  W x H - \_\_\_\_\_

Material - GRAVEL Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C


Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

Just observed

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 150



Parkins  
lot



Restrooms



Black Creek

X

Spring



X

Pond



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 647 Date: 6/11/82 Time: 10:45 Crew: 2

Weather: Today - Cloudy

Yesterday - Cloudy

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: Greenhorn spring in basement

(Sketch on back) Well, south of parking lot  
(See # 645)

Outfall Description: Size - POND  $\phi$  W x H - \_\_\_\_\_

Material - \_\_\_\_\_ Shape - \_\_\_\_\_

Active: Y / N Photographed: Y / N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

Seepage water

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 647



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 47 Date: 9/14/82 Time: 2:15 Crew: 1 - JMI

Weather: Today - overcast

Yesterday - clear

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: Drinking water # 107 Whitman Ave.  
(Sketch on back)

Outfall Description: Size - 375  $\phi$  W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: 100 #17

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - 1100 L/sec

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED



Page 1 of 1

Section 1		Section 2		Section 3	
Item 1		Item 2		Item 3	
Item 4		Item 5		Item 6	
Item 7		Item 8		Item 9	
Item 10		Item 11		Item 12	
Item 13		Item 14		Item 15	
Item 16		Item 17		Item 18	
Item 19		Item 20		Item 21	
Item 22		Item 23		Item 24	
Item 25		Item 26		Item 27	
Item 28		Item 29		Item 30	
Item 31		Item 32		Item 33	
Item 34		Item 35		Item 36	
Item 37		Item 38		Item 39	
Item 40		Item 41		Item 42	
Item 43		Item 44		Item 45	
Item 46		Item 47		Item 48	
Item 49		Item 50		Item 51	
Item 52		Item 53		Item 54	
Item 55		Item 56		Item 57	
Item 58		Item 59		Item 60	
Item 61		Item 62		Item 63	
Item 64		Item 65		Item 66	
Item 67		Item 68		Item 69	
Item 70		Item 71		Item 72	
Item 73		Item 74		Item 75	
Item 76		Item 77		Item 78	
Item 79		Item 80		Item 81	
Item 82		Item 83		Item 84	
Item 85		Item 86		Item 87	
Item 88		Item 89		Item 90	
Item 91		Item 92		Item 93	
Item 94		Item 95		Item 96	
Item 97		Item 98		Item 99	
Item 100		Item 101		Item 102	
Item 103		Item 104		Item 105	
Item 106		Item 107		Item 108	
Item 109		Item 110		Item 111	
Item 112		Item 113		Item 114	
Item 115		Item 116		Item 117	
Item 118		Item 119		Item 120	
Item 121		Item 122		Item 123	
Item 124		Item 125		Item 126	
Item 127		Item 128		Item 129	
Item 130		Item 131		Item 132	
Item 133		Item 134		Item 135	
Item 136		Item 137		Item 138	
Item 139		Item 140		Item 141	
Item 142		Item 143		Item 144	
Item 145		Item 146		Item 147	
Item 148		Item 149		Item 150	
Item 151		Item 152		Item 153	
Item 154		Item 155		Item 156	
Item 157		Item 158		Item 159	
Item 160		Item 161		Item 162	
Item 163		Item 164		Item 165	
Item 166		Item 167		Item 168	
Item 169		Item 170		Item 171	
Item 172		Item 173		Item 174	
Item 175		Item 176		Item 177	
Item 178		Item 179		Item 180	
Item 181		Item 182		Item 183	
Item 184		Item 185		Item 186	
Item 187		Item 188		Item 189	
Item 190		Item 191		Item 192	
Item 193		Item 194		Item 195	
Item 196		Item 197		Item 198	
Item 199		Item 200		Item 201	
Item 202		Item 203		Item 204	
Item 205		Item 206		Item 207	
Item 208		Item 209		Item 210	
Item 211		Item 212		Item 213	
Item 214		Item 215		Item 216	
Item 217		Item 218		Item 219	
Item 220		Item 221		Item 222	
Item 223		Item 224		Item 225	
Item 226		Item 227		Item 228	
Item 229		Item 230		Item 231	
Item 232		Item 233		Item 234	
Item 235		Item 236		Item 237	
Item 238		Item 239		Item 240	
Item 241		Item 242		Item 243	
Item 244		Item 245		Item 246	
Item 247		Item 248		Item 249	
Item 250		Item 251		Item 252	
Item 253		Item 254		Item 255	
Item 256		Item 257		Item 258	
Item 259		Item 260		Item 261	
Item 262		Item 263		Item 264	
Item 265		Item 266		Item 267	
Item 268		Item 269		Item 270	
Item 271		Item 272		Item 273	
Item 274		Item 275		Item 276	
Item 277		Item 278		Item 279	
Item 280		Item 281		Item 282	
Item 283		Item 284		Item 285	
Item 286		Item 287		Item 288	
Item 289		Item 290		Item 291	
Item 292		Item 293		Item 294	
Item 295		Item 296		Item 297	
Item 298		Item 299		Item 300	
Item 301		Item 302		Item 303	
Item 304		Item 305		Item 306	
Item 307		Item 308		Item 309	
Item 310		Item 311		Item 312	
Item 313		Item 314		Item 315	
Item 316		Item 317		Item 318	
Item 319		Item 320		Item 321	
Item 322		Item 323		Item 324	
Item 325		Item 326		Item 327	
Item 328		Item 329		Item 330	
Item 331		Item 332		Item 333	
Item 334		Item 335		Item 336	
Item 337		Item 338		Item 339	
Item 340		Item 341		Item 342	
Item 343		Item 344		Item 345	
Item 346		Item 347		Item 348	
Item 349		Item 350		Item 351	
Item 352		Item 353		Item 354	
Item 355		Item 356		Item 357	
Item 358		Item 359		Item 360	
Item 361		Item 362		Item 363	
Item 364		Item 365		Item 366	
Item 367		Item 368		Item 369	
Item 370		Item 371		Item 372	
Item 373		Item 374		Item 375	
Item 376		Item 377		Item 378	
Item 379		Item 380		Item 381	
Item 382		Item 383		Item 384	
Item 385		Item 386		Item 387	
Item 388		Item 389		Item 390	
Item 391		Item 392		Item 393	
Item 394		Item 395		Item 396	
Item 397		Item 398		Item 399	
Item 400		Item 401		Item 402	
Item 403		Item 404		Item 405	
Item 406		Item 407		Item 408	
Item 409		Item 410		Item 411	
Item 412		Item 413		Item 414	
Item 415		Item 416		Item 417	
Item 418		Item 419		Item 420	

# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 651 Date: 11/11/82 Time: 2:00 Crew: ...

Weather: Today - Some Rain  
Yesterday - Clear

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: Above Downman Bldg. Humber School area,

(Sketch on back) small tributary E. of #371  
(South of Sunnyside, N. of Appleton Ct.)

Outfall Description: Size - Indeterminate  $\phi$  W x H - \_\_\_\_\_

Material - \_\_\_\_\_ Shape - \_\_\_\_\_

Active: (Y) N Photographed: (Y) N #: RAW #12-12

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

1.2/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C


Conductivity: 975 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

Clear - some dirt Barrel

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 453 Date: 11/11/82 Time: 2:15 Crew: JH, JH

Weather: Today - Some rain

Yesterday - Clearcast

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: End of Tributary from #371 at Delcrest  
(Sketch on back) Decks

S. of #135 Sunfield, W. of Wycombe Street

Outfall Description: Size - 600 @ W x H - \_\_\_\_\_

Material - Concrete Shape - Irregular

Active: Y/N Photographed: Y/N #: Red 19-15

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other Phenol

Flow Rate: Velocity - \_\_\_\_\_

1.2, sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: 9.8 mg/L Air Temp.: 3 °C

pH: 7.9 Water Temp.: 11 °C

Conductivity 825 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

Concrete Street Light

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: 15-19-15

21

Date		Description		Amount	
1890	Jan 1	Balance		100.00	
	Jan 15	Received from A. B.		50.00	
	Feb 1	Received from C. D.		25.00	
	Feb 15	Received from E. F.		75.00	
	Mar 1	Received from G. H.		100.00	
	Mar 15	Received from I. J.		50.00	
	Apr 1	Received from K. L.		25.00	
	Apr 15	Received from M. N.		75.00	
	May 1	Received from O. P.		100.00	
	May 15	Received from Q. R.		50.00	
	Jun 1	Received from S. T.		25.00	
	Jun 15	Received from U. V.		75.00	
	Jul 1	Received from W. X.		100.00	
	Jul 15	Received from Y. Z.		50.00	
	Aug 1	Received from A. B.		25.00	
	Aug 15	Received from C. D.		75.00	
	Sep 1	Received from E. F.		100.00	
	Sep 15	Received from G. H.		50.00	
	Oct 1	Received from I. J.		25.00	
	Oct 15	Received from K. L.		75.00	
	Nov 1	Received from M. N.		100.00	
	Nov 15	Received from O. P.		50.00	
	Dec 1	Received from Q. R.		25.00	
	Dec 15	Received from S. T.		75.00	
	Total			1000.00	



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 655 Date: 12/11/82 Time: 2:30 Crew: 1st crew

Weather: Today - Rain

Yesterday - Rain - periodic

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: Intersection of Denbigh & Whitburn Cr.

(Sketch on back) South of Tributary @ # 367  
West of Outfall # 375

Outfall Description: Size - 300 W x H - \_\_\_\_\_

Material - Concrete Shape - Rectangular

Active: (Y) N Photographed: (Y) N #: Roll # 12 17

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Trickle Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: / mg/L Air Temp.: \_\_\_\_\_ °C

pH: / Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

very severe  
clean - stagnant water

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 652 Date: 5/11/80 Time: \_\_\_\_\_ Crew: 24158

Weather: Today - Cloudy

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: on the east bank of the river

(Sketch on back) going under the bridge

Outfall Description: Size - 1200 W x H - \_\_\_\_\_

Material - UP Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: 10017-10

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: 7 mg/L Air Temp.: 23 °C

pH: 7.2 Water Temp.: 9 °C

Conductivity: 1000 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 156



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 650 Date: 15/11/82 Time: \_\_\_\_\_ Crew: \_\_\_\_\_

Weather: Today - cloudy & rain

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: at the west end of the Humber River

(Sketch on back) 2. west going and north

Outfall Description: Size - ~75' W x H - \_\_\_\_\_

Material - 71' Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: 650-14-70

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: 11 mg/L Air Temp.: 3 °C

pH: 7.9 Water Temp.: 5 °C

Conductivity 160 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: BC 157



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 601 Date: 8/11/00 Time: 3:00 Crew: \_\_\_\_\_

Weather: Today - \_\_\_\_\_

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: immediately upstream of

(Sketch on back)

Outfall Description: Size - 100 W x H - \_\_\_\_\_

Material - CT Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED





(Sketch on back)

Conductivity: \_\_\_\_\_ umhos

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED



THE UNIVERSITY OF CHICAGO  
LIBRARY

1962  
1963  
1964  
1965  
1966  
1967  
1968  
1969  
1970  
1971  
1972  
1973  
1974  
1975  
1976  
1977  
1978  
1979  
1980  
1981  
1982  
1983  
1984  
1985  
1986  
1987  
1988  
1989  
1990  
1991  
1992  
1993  
1994  
1995  
1996  
1997  
1998  
1999  
2000  
2001  
2002  
2003  
2004  
2005  
2006  
2007  
2008  
2009  
2010  
2011  
2012  
2013  
2014  
2015  
2016  
2017  
2018  
2019  
2020  
2021  
2022  
2023  
2024  
2025

1962  
1963  
1964  
1965  
1966  
1967  
1968  
1969  
1970  
1971  
1972  
1973  
1974  
1975  
1976  
1977  
1978  
1979  
1980  
1981  
1982  
1983  
1984  
1985  
1986  
1987  
1988  
1989  
1990  
1991  
1992  
1993  
1994  
1995  
1996  
1997  
1998  
1999  
2000  
2001  
2002  
2003  
2004  
2005  
2006  
2007  
2008  
2009  
2010  
2011  
2012  
2013  
2014  
2015  
2016  
2017  
2018  
2019  
2020  
2021  
2022  
2023  
2024  
2025

1962  
1963  
1964  
1965  
1966  
1967  
1968  
1969  
1970  
1971  
1972  
1973  
1974  
1975  
1976  
1977  
1978  
1979  
1980  
1981  
1982  
1983  
1984  
1985  
1986  
1987  
1988  
1989  
1990  
1991  
1992  
1993  
1994  
1995  
1996  
1997  
1998  
1999  
2000  
2001  
2002  
2003  
2004  
2005  
2006  
2007  
2008  
2009  
2010  
2011  
2012  
2013  
2014  
2015  
2016  
2017  
2018  
2019  
2020  
2021  
2022  
2023  
2024  
2025

# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 625-665 Date: 16/11/82 Time: 11:30 Crew: 11 & D1

Weather: Today - Sunny - Cool

Yesterday - -

River: Humber Main Black Creek Humber West Other: Trick

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: North of Finch Ave Culvert, E.W. of Thornhill

(Sketch on back) (W. Bank) Approx 10m N.

Outfall Description: Size - 300 W x H - Ø

Material - CMR Shape - Ø

Active: NO Photographed: Y N #:       

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other       

Flow Rate: Velocity -       

Depth -       

Sketch cross-section shape (on back)

Field Tests: D.O.:        mg/L Air Temp.:        °C

None pH:        Water Temp.:        °C

Conductivity:        umhos

Observations: Colour Odour Erosion Impacts Land Use Other:       

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boot Only

Is outfall otherwise mapped? Map:        #: NOT MAPED



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # ~~1152~~ <sup>1152</sup> Date: 16/11/52 Time: 10:25 Crew: 10/5/54

Weather: Today - Sunny - Cool

Yesterday - —

River: Humber Main Black-Creek Humber West Other: Trick

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: Beneath Poplar Road - Culvert

(Sketch on back) W. of Tobermory.

Outfall Description: Size - ?  $\phi$  W x H - —

Material - — Shape - —

Active: (Y) <sup>Trickle</sup> N Photographed: (Y) N #: hole #17-36

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other —

Flow Rate: Velocity - —

Depth - —

Sketch cross-section shape (on back)

Field Tests: D.O.: — mg/L Air Temp.: — °C

Inaccessible pH: — Water Temp.: — °C

Conductivity: — umhos

Observations: Colour Odour Erosion Impacts Land Use Other: Some gas from water

ACCESSIBILITY: Easy Difficult Road Foot Monhole Boat Only Feet

Is outfall otherwise mapped? Map: — #: NOT MAPPED



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 669 Date: 10/11/82 Time: 10:30 Crew: JH & AM

Weather: Today - Sunny - Cool

Yesterday - 11

River: Humber Main Black Creek Humber West Other: Tributary

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: At Driftwood Avenue, underneath road

(Sketch on back) S of Edley Edley Park.

Outfall Description: Size - 450 W x H - 8

Material - concrete Shape - rectangular

Active: Y N Photographed: Y N #: Roll # 10 22

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other none

Flow Rate: Velocity - 10/sec

Depth - 10

Sketch cross-section shape (on back)

Field Tests: D.O.: — mg/L Air Temp.: — °C

pH: — Water Temp.: — °C

Conductivity: 900 umhos

Observations: Colour cloudy Odour street Erosion Deposits in Land Use channel Other: —

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: — #: NOT MAPPED





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 111 Date: 5/11/80 Time: 2:00 Crew: 111

Weather: Today - \_\_\_\_\_  
Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto  
G H I J K L York North York  
M N O P Q

Location: Section 6, 11, 377 in W. Humber  
(Sketch on back) approx. 25m, 10m upstream

Outfall Description: Size - 300  $\phi$  W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: 111

Samples Collected: Bacteria Routine Chemical  
Metals Organic  
Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_  
Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C  
pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C  
Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only  
Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 673 Date: 16/11/82 Time: 11:15 Crew: J.M.C.M.

Weather: Today - Sunny - Cool

Yesterday - —

River: Humber Main Black Creek Humber West Other: Trib

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: North of Dwyer Ave. in Edgewood

(Sketch on back) (E. Bank) Approx. 10m Ponds

Outfall Description: Size - 300 @ W x H - —

Material - CMP Shape - —

Active: Y/N Photographed: Y/N #: —

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other —

Flow Rate: Velocity - —

Depth - —

Sketch cross-section shape (on back)

Field Tests: D.O.: — mg/L Air Temp.: — °C

pH: — Water Temp.: — °C

Conductivity: — umhos

Observations: Colour Odour Erosion Impacts Land Use Other: —

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: — #: NOT MAPPED



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 075 Date: 6/14/82 Time: 1:15 Crew: J. Lee

Weather: Today - Cloudy - 10°C

Yesterday - Clear - 20°C

River: Humber Main Black Creek Humber West Other: Trill

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P

Location:

(Sketch on back) In pool of water under Trill

Outfall Description: Size - 300 W x H - 100

Material - CRIP Shape - Circle

Active: Y/N TRICKLE Photographed: Y/N #: 1

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other 100

Flow Rate: Velocity - 1

1/100 L/sec Depth - 1

Sketch cross-section shape (on back)

Field Tests: D.O.: — mg/L Air Temp.: — °C

pH: — Water Temp.: — °C

Conductivity: 1500 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: — #: NOT MAPPED



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 617 Date: 8/1/82 Time: \_\_\_\_\_ Crew: D.L. Lee

Weather: Today - Partly Cloudy

Yesterday - Clear

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: on the south bank of the west of the

(Sketch on back) of the Finch Ave bridge west of Triangle

Outfall Description: Size - 375 @ W x H - \_\_\_\_\_

Material - CIP Shape - \_\_\_\_\_

Active: (Y/N) Photographed: (Y/N) #: Row 12-

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other

Flow Rate: 1100 Velocity - \_\_\_\_\_

litre/sec

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: ~10 °C

pH: 7.1 Water Temp.: \_\_\_\_\_ °C

Conductivity: 200 umhos


Observations: Colour Odour Erosion Impacts Land Use Other:

clear no no no no

ACCESSIBILITY: Easy Difficult Road Foot Monhole Boat Only

Is outfall otherwise mapped? Map: 41209 #: NOT MAPPED

ENTRAN-82HU





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 619 Date: 18/11/82 Time: \_\_\_\_\_ Crew: D. Lee

Weather: Today - Cloudy

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ south of Rowntree Mill Rd & near 10th

(Sketch on back) of 73 Rowntree Mill Rd

Outfall Description: Size - ~1500 W x H - \_\_\_\_\_

Material - Concrete Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: Row 13-22

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: 1.00 litre/sec Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp: 10 °C



pH: 7.3 Water Temp: \_\_\_\_\_ °C

Conductivity: 1350 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED



Rauvutnee Hill Rd

# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 681 Date: 18/11/82 Time: 2:35 Crew: JHE/ML

Weather: Today - Sunny - Cool

Yesterday - h

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: S. of Steeles Ave. Bridge, SW 1/4 of  
(Sketch on back) Outfall # 477

Outfall Description: Size - 600 Ø W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: 101-17-29

Samples Collected: Bacteria Routine Chemical

Pure Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boot Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: NOT MAPPED



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 105 Date: 22/11/82 Time: 2:30 Crew: 11:16M

Weather: Today - Sunny - Cool  
Yesterday -                     

River: Humber Main Black Creek Humber West Other:                     

Reach: (A) B C D E F Borough: Etobicoke Toronto  
G H I J K L York North York  
M N O P Q

Location: 50m S. of Lakeshore Ave Bridge on E. Side  
(Sketch on back) g Retaining Wall - Submerged

Outfall Description: Size - 750 Ø W x H -                     

Material - CMP Shape -                     

Active: Y/N ? Photographed: (Y) N #:                     

Samples Collected: Bacteria Routine Chemical  
None Metals Organic  
Other                     

Flow Rate: Velocity -                       
? Depth -                     

Sketch cross-section shape (on back)

Field Tests: D.O.:                      mg/L Air Temp.:                      °C  
None pH:                      Water Temp.:                      °C  
Conductivity:                      umhos

Observations: Colour Odour Erosion Impacts Land Use Other:  
Submerged

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only  
Is outfall otherwise mapped? Map:                      #: 111



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 685 Date: 6/12/82 Time: 2:30 Crew: JH & DM

Weather: Today - cool - overcast  
Yesterday - rain

River: Humber Main Black Creek Humber West Other: Silver Creek

Reach: A B C D E F Borough: Etobicoke Toronto  
G H I J K L Xorin North York  
M N O P Q

Location: 25m up of Edenbridge Dr. S. side  
(Sketch on back)  
- small watercourse that drains surrounding  
(ground water) hills

Outfall Description: Size - 400 B.W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

~ 2-3 c/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp: 9 °C


Conductivity 750 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

none none

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 257 Date: 7/12/82 Time: \_\_\_\_\_ Crew: \_\_\_\_\_

Weather: Today - cloudy, 10°C

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~150m upstream of Humber Falls (bridge 4/5) ~ 100m

(Sketch on back) near the local

Outfall Description: Size - 300 W x H - \_\_\_\_\_

Material - CM Shape - \_\_\_\_\_

Active: Y / N Photographed: Y / N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: ~8 °C

pH: \_\_\_\_\_ Water Temp.: 6 °C

Conductivity: 650 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 157 Date: 6/17/82 Time: \_\_\_\_\_ Crew: 24-11

Weather: Today - \_\_\_\_\_

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~ 165 + 0/3 of Humber River bridge in Toronto

(Sketch on back)

Outfall Description: Size - 200 W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N # \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: 3 °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: 225 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 291 Date: 7/12/82 Time: \_\_\_\_\_ Crew: DH & JH

Weather: Today - \_\_\_\_\_

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: Liver Creek

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: ~20 m west of #55 on the south bank

(Sketch on back)

Outfall Description: Size - 300 @ W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

No Metals Organic

Other \_\_\_\_\_

Flow Rate: \_\_\_\_\_ Velocity - \_\_\_\_\_

slight  $\frac{1}{10}$  L/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp: \_\_\_\_\_ °C

No pH: \_\_\_\_\_ Water Temp: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

clear

-draining swamps

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 695 Date: 7/12/82 Time: \_\_\_\_\_ Crew: DMTH

Weather: Today - \_\_\_\_\_

Yesterday - \_\_\_\_\_

River: Humber Main ☐ Black Creek ☐ Humber West ☐ Other: Liver Creek

Reach: A B ☒ D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: on the north side of ROYAL YORK Rd & south of  
(Sketch on back) NORTH DR, ~65M SOUTH of NORTH DR.

Outfall Description: Size - 300 ☒ W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y/☒ Photographed: ☒ N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

No Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

No Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp: \_\_\_\_\_ °C


No pH: \_\_\_\_\_ Water Temp: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 695 Date: 7/12/82 Time: \_\_\_\_\_ Crew: \_\_\_\_\_

Weather: Today - \_\_\_\_\_

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: Liver Creek

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: On the north side of ROYAL YORK DR & south  
(Sketch on back) of NORTH DR., ~55M SOUTH of NORTH DR

Outfall Description: Size - 300 @ W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y / N Photographed: Y / N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C


Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

- collapsed

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 697 Date: 13/12/82 Time: 2:30 Crew: M. DM

Weather: Today - Cold - Overcast

Yesterday - — 11 — 12 —

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q @ side

Location: Behind #218 Oakdale Street (Between) #310

(Sketch on back) @ side of Hwy 400 General Refrigeration  
1st 218 N.W. corner of Complex Company

Outfall Description: Size - 1200 @ W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: Y (N) Photographed: (Y) N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

100 pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: None



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 699 Date: 15/12/82 Time: 9:40 Crew: J.H. & M.

Weather: Today - cool - overcast

Yesterday - — 1 — 11 —

River: Humber Main Black Creek Humber West Other: Tributary to #293

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: 30m W of Fortlinchys Cres

(Sketch on back) 30m W of Culvert inlet before it goes under  
50 N of Heathrow Dr.

Outfall Description: Size - 450 Ø W x H - —

Material - CMP Shape - —

Active: (Y) N Photographed: (Y) N #: —

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other —

Flow Rate: Velocity - —

1/10 c/sec Depth - —

Sketch cross-section shape (on back)

Field Tests: D.O.: — mg/L Air Temp.: — °C

pH: — Water Temp.: — °C

Conductivity: 2750 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

clear none

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: — #: —



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 701 Date: 15/12/82 Time: 9:45 Crew: 241 & DM

Weather: Today - Cool - overcast

Yesterday - 11

River: Humber Main Black Creek Humber West Other: Trip #273

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: Same as # 699. (intersection of Humber & Forth York)  
(Sketch on back) 5 m w/s of underground electric culvert

Outfall Description: Size - 400  $\phi$  W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: (Y) N Truck Photographed: (Y) N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Yes Metals shovel Organic

Flow Rate: Velocity - \_\_\_\_\_

Truck 100 1/500 Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: 8.4 Water Temp.: \_\_\_\_\_ °C

Conductivity: 1150 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

on bank  
rusty discharge - gas film

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 703 Date: 15/12/82 Time: 9:50 Crew: JH & DM

Weather: Today - leaf - clear

Yesterday - leaf - clear

River: Humber Main Black Creek Humber West Other: Trib

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: S.E. of Hazel Rd

(Sketch on back) 40m/s of # 697

Outfall Description: Size - 250 W x H -         

Material - CMP Shape -         

Active: Q/N Photographed: (Y/N) #:         

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other phenol

Flow Rate: Velocity -         

1/4 l/sec Depth -         

Sketch cross-section shape (on back)

Field Tests: D.O.:          mg/L Air Temp.:          °C

pH: 8.1 Water Temp.:          °C

Conductivity: 1680 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:         

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map:          #:



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 705 Date: 15/12/82 Time: 13:55 Crew: J.H.S.D.M.

Weather: Today - Cool - Overcast

Yesterday -                     

River: Humber Main Black Creek Humber West Other: Trill

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: 5 m U/S of #703

(Sketch on back)

Outfall Description: Size - 300  $\phi$  W x H -                     

Material - CMP Shape -                     

Active: Y N Photographed: Y N # :                     

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other                     

Flow Rate: Velocity -                     

Depth -                     

Sketch cross-section shape (on back)

Field Tests: D.O. :                      mg/L Air Temp.:                      °C

None pH :                      Water Temp.:                      °C

Conductivity                      umhos

Observations: Colour Odour Erosion Impacts Land Use Other :                     

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped ? Map:                      #:



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 707 Date: 15/12/82 Time: 10.00 Crew: JH & DM

Weather: Today - cool - Overcast

Yesterday - 1

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: N.W. of Tavistock Rd - 15m

(Sketch on back) South of Exbury Pk. on S. bank

@ Foot bridge

Outfall Description: Size - 600 Ø W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y N Photographed: Y N # : \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O : \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH : \_\_\_\_\_ Water Temp. : \_\_\_\_\_ °C

Conductivity : \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other : \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped ? Map: \_\_\_\_\_ # : \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 709 Date: 15/12/82 Time: \_\_\_\_\_ Crew: \_\_\_\_\_

Weather: Today - \_\_\_\_\_

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: Trib

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: Same as # 707

(Sketch on back) N. Bank.

Outfall Description: Size - 300 (p) W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y N Photographed: Y N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 711 Date: 5/12/82 Time: 0:10 Crew: JH & DM

Weather: Today - Cloud - Clear

Yesterday - 11

River: Humber Main Black Creek Humber West Other: Tail

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: N of Toronto Rd.

(Sketch on back) S. of Exbury; Sinton et. [S. bank on

[Approx. 200m W/S of # 709, 707] Watercourse  
5m

Outfall Description: Size - 400 Ø W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y N Photographed: Y N # : \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O. : \_\_\_\_\_ mg/L Air Temp : \_\_\_\_\_ °C

None pH : \_\_\_\_\_ Water Temp : \_\_\_\_\_ °C


Conductivity : \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other :

Yes

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped ? Map: \_\_\_\_\_ # : \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 713 Date: 15/12/82 Time: 10:15 Crew: \_\_\_\_\_

Weather: Today - \_\_\_\_\_

Yesterday - \_\_\_\_\_

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto  
G H I J K L York North York  
M N O P Q

Location: Same as # 711 - N bank  
(Sketch on back) S. of Exbury Rd. on Sm Watercourse

Outfall Description: Size - 300  $\phi$  W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: ☒ N Photographed: ☒ N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 715 Date: 15/12/82 Time: 10:15 Crew: JH & DM  
Weather: Today - Cool - Overcast  
Yesterday - 1 -

River: Humber Main Black Creek Humber West Other: Trib - #270  
Reach: A B C D E F Borough: Etobicoke Toronto  
G H I J K L York North York  
M N O P Q


Location: 10m N of Tauxstock Rd. in Tauxstock Park  
(Sketch on back) U of Exbury Rd.  
35m N of (source of Trib)

Outfall Description: Size - 1050 O W x H -           
Material - CMP Shape -           
Active: Y N Photographed: Y N #:         

Samples Collected: Bacteria Routine Chemical  
Metals Organic  
Other Phenol  
Flow Rate: 10 l/sec  
Velocity -           
Depth -         

Sketch cross-section shape (on back)  
Field Tests: D.O.:          mg/L Air Temp.:          °C  
pH: 8.1 Water Temp.:          °C  
Conductivity: 1700 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: 900 film  
ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only  
Is outfall otherwise mapped? Map:          #:



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 717 Date: 15/12/82 Time: 11:30 Crew: \_\_\_\_\_

Weather: Today - Cool - Windy

Yesterday - 11

River: Humber Main Black Creek Humber West Other: #225 Trib

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L Yark North York

M N P Q

Location: 40 m S. along watercourse, SE. of hole  
(Sketch on back) N. of NORTH Rd @ 1st bend of  
#36 Rd  creek

Outfall Description: Size - 300 Ø W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y N Photographed: (Y) N # : \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 719 Date: 15/12/82 Time: 10:11:15 Crew: JH & DM

Weather: Today - Cool - Overcast

Yesterday - —

River: Humber Main Black Creek Humber West Other: #225 Tails

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: 5 m v/s of Foot bridge @ Maple leaf Dr.  
(Sketch on back)

Outfall Description: Size - 200  $\phi$  W x H - —

Material - Concrete Shape - —

Active: (Y) N Tackle Photographed: (Y) N # : —

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other —

Flow Rate: Velocity - —

Depth - —

Sketch cross-section shape (on back)

Field Tests: D.O. : — mg/L Air Temp.: — °C

pH : — Water Temp.: — °C

Conductivity: 1525 umhos

Observations: Colour Odour Erosion Impacts Land Use Other

high! small


ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: — # : —

Maple leaf drive?

#719

Foot  
Bridge



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 721 Date: 16/12/82 Time: 11:15 Crew: JHE DTH

Weather: Today - Rain

Yesterday - Cool - Breeze

River: Humber Main Black Creek Humber West Other: #225 Trib

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: 30m W. of Tree lawn Hwy 40m N. of North bank  
(Sketch on back) in Gully Map

Outfall Description: Size - 300 Ø W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: (Y) N Photographed: (Y) N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

2 L/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: 650 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

clean some no erosion

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 723 Date: 15/10/82 Time: 11:20 Crew: 21 DMI

Weather: Today - RAIN

Yesterday - COOL - CLEAR

River: Humber Main Black Creek Humber West Other: #225 TAIL

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q 5m up bank on

Location: 15M D/S of #721 N Bank, S. of bridge

(Sketch on back) Ridge

(N.B. 3" clay pipe beside outfall)

Outfall Description: Size - 300 W x H - 8

Material - Concrete Shape -

Active: (Y) N Photographed: (Y) N #:

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other

Flow Rate: Velocity -

Trickle Depth -

Sketch cross-section shape (on back)

Field Tests: D.O. :  mg/L Air Temp:  °C

pH:  Water Temp:  °C

Conductivity:  umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

Some

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map:  #:



THE UNIVERSITY OF CHICAGO  
LIBRARY

THE UNIVERSITY OF CHICAGO  
LIBRARY  
1100 EAST 58TH STREET  
CHICAGO, ILL. 60637  
TEL. (312) 937-1234  
FAX (312) 937-1234  
WWW.CHICAGO.EDU

THE UNIVERSITY OF CHICAGO  
LIBRARY  
1100 EAST 58TH STREET  
CHICAGO, ILL. 60637  
TEL. (312) 937-1234  
FAX (312) 937-1234  
WWW.CHICAGO.EDU

THE UNIVERSITY OF CHICAGO  
LIBRARY  
1100 EAST 58TH STREET  
CHICAGO, ILL. 60637  
TEL. (312) 937-1234  
FAX (312) 937-1234  
WWW.CHICAGO.EDU

# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 725 Date: 16/12/82 Time: 1:30 Crew: JH: DM

Weather: Today - Rain & Snow

Yesterday - Cool - Clear

River: Humber Main Black Creek Humber West Other: #225 Trib

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: 70 m up watercourse, W. of Railroad tracks  
(Sketch on back) Approx 150 m N/S of Rustic Road @ Foot bridge

Outfall Description: Size - 900 (R-450) Ø W x H - Arch

Material - Concrete Shape - \_\_\_\_\_

Active: (Y) N Photographed: (Y) N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

~ 8-10 l/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O. : \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH : \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: 310 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

- cloudy

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_

17. The following table shows the number of people who attended the concert on each day of the week.

Day	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday
Number of people	120	150	180	200	220	250	280

18. The following table shows the number of people who attended the concert on each day of the week.

Day	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday
Number of people	120	150	180	200	220	250	280

19. The following table shows the number of people who attended the concert on each day of the week.

Day	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday
Number of people	120	150	180	200	220	250	280

20. The following table shows the number of people who attended the concert on each day of the week.

Day	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday
Number of people	120	150	180	200	220	250	280

21. The following table shows the number of people who attended the concert on each day of the week.

Day	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday
Number of people	120	150	180	200	220	250	280

22. The following table shows the number of people who attended the concert on each day of the week.

Day	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday
Number of people	120	150	180	200	220	250	280

23. The following table shows the number of people who attended the concert on each day of the week.



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 727 Date: 16/12/82 Time: 1.45 Crew: JH & DM

Weather: Today - Rain - Snow

Yesterday - Cool - Overcast

River: Humber Main Black Creek Humber West Other: #225 Trib

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: 75m N of Rustic road on E. Bank.

(Sketch on back) W. of railroad tracks.

Outfall Description: Size - 600 @ W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y N Photographed: Y N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

32/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity 600 umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

Clear

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 729 Date: 16/12/82 Time: 1:50 Crew: JH DM

Weather: Today - Rain & Snow

Yesterday - Cool & Overcast

River: Humber Main Black Creek Humber West Other: #225 Trib

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: 50 m D/S of Ruston Road, 10 m from  
(Sketch on back) W. Bank up side of hill  
E. of Cornhill Pkwy.

Outfall Description: Size - 200 Ø W x H - \_\_\_\_\_

Material - CMP Shape - \_\_\_\_\_

Active: Y (N) Photographed: (Y) N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 731 Date: 16/12/82 Time: 2:00 Crew: HC & DLI

Weather: Today - Snow - Rain

Yesterday - Cloud - Overcast

River: Humber Main Block Creek Humber West Other: #275 Tril

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: 10 m S. of Rustic Road, E. Bank @  
(Sketch on back) Bend in Tril

Outfall Description: Size - 900 Ø W x H - \_\_\_\_\_

Material - Concrete Shape - \_\_\_\_\_

Active: Y/N Photographed: Y/N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

1 l/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O. : \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH : \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity 325 umhos

Observations: Colour Odour Erosion Impacts Land Use Other :

None

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ # : \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 733 Date: 16/12/82 Time: 2:30 Crew: JH DM

Weather: Today - Rain - Snow

Yesterday - Cool - Overcast

River: Humber Main Black Creek Humber West Other: #225 Trib

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: N. of Hwy #40 E. of RR tracks approx 100m  
(Sketch on back) #20m

Outfall Description: Size - Buried @ W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: Y N Photographed: Y N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_

<div data-bbox="62 136 155 211" data-label="Image"></div>	<div data-bbox="393 181 435 226" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 181 787 226" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 241 155 317" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 287 435 332" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 287 787 332" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 347 155 423" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 393 435 438" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 393 787 438" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 453 155 529" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 498 435 544" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 498 787 544" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 559 155 635" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 604 435 650" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 604 787 650" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 665 155 740" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 710 435 756" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 710 787 756" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 771 155 846" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 816 435 861" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 816 787 861" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 876 155 952" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 922 435 967" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 922 787 967" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 982 155 1058" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 1028 435 1073" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 1028 787 1073" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 1088 155 1164" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 1134 435 1179" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 1134 787 1179" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 1194 155 1270" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 1239 435 1285" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 1239 787 1285" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 1300 155 1375" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 1345 435 1391" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 1345 787 1391" data-label="Text"> <p>1898</p> </div>
<div data-bbox="62 1406 155 1481" data-label="Text"> <p>1898</p> </div>	<div data-bbox="393 1451 435 1496" data-label="Text"> <p>1898</p> </div>	<div data-bbox="745 1451 787 1496" data-label="Text"> <p>1898</p> </div>



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 735 Date: 16/12/82 Time: 2:45 Crew: JH Dml

Weather: Today - rain snow  
Yesterday - cool - overcast

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto  
G H I J K L York North York  
M N O P Q

Location: N. of 401 (15m), 90m E. of RR tracks  
(Sketch on back)

Outfall Description: Size - 300 Ø W x H - \_\_\_\_\_

Material - concrete Shape - \_\_\_\_\_

Active: Y N Photographed: Y N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical  
None Metals Organic  
Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_  
1/2 l / sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: — mg/L Air Temp.: — °C  
pH: — Water Temp.: — °C  
Conductivity: 150 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 737 Date: 16/12/82 Time: \_\_\_\_\_ Crew: HL DM

Weather: Today - Rain Snow

Yesterday - cool

River: Humber Main Black Creek Humber West Other: \_\_\_\_\_

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: N. of Hwy 401 - 20 m 50 m E of

(Sketch on back)  
- blocked up by mortar and bricks RR tracks

Outfall Description: Size - 1500 Ø W x H - \_\_\_\_\_

Material - Concrete Shape - \_\_\_\_\_

Active: (N) Photographed: (Y) N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

None Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

None Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

None pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 739 Date: 16/12/82 Time: \_\_\_\_\_ Crew: JH DM

Weather: Today - Rain - Snow

Yesterday - Cool

River: Humber Main Black Creek Humber West Other: #225 Trail

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: 20m N. of 401 - 30m E. RR tracks.  
(Sketch on back) directly across from inlet under 401

Outfall Description: Size - 2000  $\phi$  W x H - \_\_\_\_\_

Material - Cincolet Shape - \_\_\_\_\_

Active: Y N Photographed: Y N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Yes Metals Organic

Other Phenol

Flow Rate: Velocity - \_\_\_\_\_

0.5 l/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: 10.8 Water Temp.: \_\_\_\_\_ °C

Conductivity: 1900 umhos

Observations: Colour Odour Erosion Impacts Land Use Other

gas bubbles in water

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_



# FIELD DATA SHEET

## Humber River Outfall Study



Outfall # 741 Date: 16/12/82 Time: 3:15 Crew: JHL DM

Weather: Today - Rain - Cool  
Yesterday - Cool

River: Humber Main Black-Creek Humber West Other: #225 Trib

Reach: A B C D E F Borough: Etobicoke Toronto  
G H I J K L Yark North York

M N O P Q #951 Source of Trib

Location: S. Salomon Ave (50m), W side of  
(Sketch on back) RR Tracks & KUN Yard  
Behind

Outfall Description: Size - 750 @ W x H - \_\_\_\_\_

Material - Cement Shape - \_\_\_\_\_

Active: (Y) N Photographed: (Y) N #: \_\_\_\_\_

Samples Collected: Bacteria Routine Chemical

Yes Metals Organic  
Other Phenol

Flow Rate: Velocity - \_\_\_\_\_

5 l/sec Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

pH: 8.0 Water Temp.: \_\_\_\_\_ °C

Conductivity: 725 umhos

Observations: Colour Odour Erosion Impacts Land Use Other: \_\_\_\_\_

g.p. filter

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_





# FIELD DATA SHEET

## Humber River Outfall Study



Outfall ~~1452~~ <sup>1454</sup> Date: 11/23/82 Time: 9:00 Crew: 754

Weather: Today - 1452

Yesterday - C

River: Humber Main Black Creek Humber West Other: T

Reach: A B C D E F Borough: Etobicoke Toronto

G H I J K L York North York

M N O P Q

Location: North Humber River Outfall

(Sketch on back)

Outfall Description: Size - 45" x 28"  $\phi$  W x H - \_\_\_\_\_

Material - CMR Shape - \_\_\_\_\_

Active: Y/N Photographed: Y N #: 8-210

Samples Collected: Bacteria Routine Chemical

NONE Metals Organic

Other \_\_\_\_\_

Flow Rate: Velocity - \_\_\_\_\_

NONE Depth - \_\_\_\_\_

Sketch cross-section shape (on back)

Field Tests: D.O.: \_\_\_\_\_ mg/L Air Temp.: \_\_\_\_\_ °C

NONE pH: \_\_\_\_\_ Water Temp.: \_\_\_\_\_ °C

Conductivity: \_\_\_\_\_ umhos

Observations: Colour Odour Erosion Impacts Land Use Other:

4

ACCESSIBILITY: Easy Difficult Road Foot Manhole Boat Only

Is outfall otherwise mapped? Map: \_\_\_\_\_ #: \_\_\_\_\_

2

